

This & contained presentations

- Scribd: <u>www.scribd.com/brianspecman</u> > collection > SusCon Retrofitting
- http://www.scribd.com/document_collections/2401889





Cath Hassell of EcH₂O



- Learning Lessons
- from past & current projects
- Resource Efficiency · Community issues
- · reinforced by recent government activity Recent Refurbishment & Retrofit

© NGS+ECH2O 2010 BrianMurphyCathHassellRetrofittin

- Blue Sky Or Green Facade Thinking
- Case Studies



Past Inheritance v bad refurbishment

- · 70's and 80's grant driven refurbishment
- · Inadequate Energy saving insulation to attics · Inappropriate inadequate windows removing
- good sashes and destroying building appearance Cement renders to cover up botched walls to
- help destroy the lime mortar brickwork integrity · Heavy concrete roofing tiles to replace adequate
- roofing slates overloading roof timbers Damp Proof Courses injected and membranes added to ground floor, modifying the moisture
- permeability and destroying great floors

	Past Mistakes
•	Major redevelopments from streets to esta New building construction methods
	 Precast loadbearing concrete panels Unskilled, uninformed, hurried labour

ection

estates

- Led to failures, some catastrophic
- Bad building design
- Concrete framed
- · Inadequate insulation/thermal bridges,
- inappropriate cheap heating adopted,
- condensation, mould, ill-health



© GreenSpec[™] 2010 Brian Murphy







Past Inheritance > Decent Homes

- · Old fashioned kitchens and bathrooms Old inefficient boilers,
 _ probably adequate heating systems
- Competent old or inadequate new windows and doors
- Competent but old un-guarantee-able roofing tiles/slates
- Mostly sent to landfill

 Some segregated and recycled

 Mostly replaced with new

 Little or no insulation:
- Inter of no insulation:

 Improved (optional v efficient boiler)
 1m properties: made decent not sustainable
 Completing: 2010



Checklists

- · Its critical to avoid unnecessary waste
- · Take every property on its own account
- Only replace if necessary
- · Formalise it and manage it
- Use tiles from one roof to repair 100 roofs
- Don't remove whole roof for the sake of two broken tiles
- · No guarantee for an old roof should never be an excuse to strip the roof © NGS+ECH2O 2010 BrianMurphyCathHassellRetrofitting



Eco Refurbishment Checklist · Decent Homes: Sustainability cop-out GreenSpec Reaction to it What can be done • 2004-2007 · Other issues need to be added - TSB Retrofit Programme learning Will be added to Downloads soon

© GreenSpec[™] 2010 Brian Murphy



Educate to Change Perception

- The day I saw those roofs I attended the Gateshead CC and ran a workshop on resource efficiency
- This catalysed a change in culture of the whole business and now all departments work as one
- · Every arising finds a reuse or a recycling opportunity
- Gateshead speak of their transformation at public events



Logistics: Materials & Waste

- 10 to 100,000 unit contracts
- Materials arising x 10 to 100,000 Set up transfer stations for materials in and waste out and materials in again
- · Consolidation centre: materials arrive off site
- Opportunity for no packaging
- · Requests for materials for days work, in advance
- · Pallets for each tradesmen/team
- · Delivered by 'milk round' to within 5m of team/space



Combine alternative approaches

- · One temporary or permanent site and/or warehouse building
- Combine resource storage, sorting for delivery and waste segregation/bulking
 Daily round trips to site(s) with JIT goods
- And daily waste and packaging collection on same
- trip · Facilitates 'take-back' 'return-to-stock' 'use or return'
- · 'Surplus to requirements' held for next site minimising 'over ordered never needed'









Excavation and Landscape

- · Site clearance: turf & topsoil stockpile
- Green waste trimmings: Composting
- Excavates subsoil: stockpiles
- Hard landscape, sub-bases, drain/service bedding/backfill: stockpile
- Subsoil & compost: Topsoil manufacture





Avoidance of bad Practice

- Place dedicated skips local at place of generation
- But not too close
- Window Deconstruction:
- · Glass skip a few paces away
- Metal fixings/ironmongery, rubber/EPDM gasket, plastic, bins closest
- or all will go in the glass skip

















Duty of Care

· Follow the waste vehicles occasionally · Check where the waste goes Ensure it reaches the destination Only pay when proof is provided

• 3 part WTN 1 for site 1 for LO/TS/RS 1 to return to site/accounts dept to check

· Extends beyond site gate







	Websites
•	www.greenstreet.org.uk
•	www.sustainingtowers.org
•	www.parityprojects.com
•	www.greenspec.co.uk/housing-refurb-retrofit.php
•	www.generationhomes.org.uk
•	www.existinghomesalliance.org
•	www.tzero.org.uk
•	www.rethinkinghousingrefurbishment.co.uk
•	www.generationhomes.org.uk

© GreenSpec[™] 2010 Brian Murphy

09/10/2010























- Old streets: accessible, understandable, visible, congested parking
- Old housing stock: competent/inadequate, adaptable, refurbish able, upgradable, extendable
- Feral un-policed youth
- Police finally admitting to failings
- Communities encouraged to take back their patch
- Major redevelopment programmes
- Repeating the 60's?
- established communities, settled families
- ^{9/10/2040} Designers fighting back with reuse proposals

Past Inheritance for Inhabitants

- Old people (non-gardeners) choose towers

 For security, avoidance of conflict with youth
- Young couples choose towers

 No time for gardens
- Young or multiple occupancy choose towers
- Avoid unrelated Young and Old in same building
 - one will overrun the other





© GreenSpec[™] 2010 Brian Murphy

7





Decent Homes Residents retreat · A room with kitchen,

dining, WC and lounge with radio

noise and the dust Allow the labour team to refurbish a

whole room in a day







1NTEGER Intelligent & Green · Radical rethink of housing provision

- · London Tower Block refurbishment example
- · Windy conditions at ground level and at
- height
- · Inadequate U value
- · Flats in towers suffer from orientation - Lack of sun. or too much
- Lack of access to satellite and/or TV signal
- · Aging population needing healthcare

· Lack of security to stairs and lifts

















- Leeds Met Uni Research highlighted issue
- BRAD L1A to be revised now



- AECB Carbon Lite advised TSB
- £150,000 budget is wholly inappropriate
- It encourages EcoBling
- £3.000 would have provided the government. with much more appropriate and useful information
- · It would have encouraged thermal insulation, thermal bridge avoidance, airtightness, weather tightness, ventilation, etc.
- Encouraged use of analysis tools other than
- SAP: PHPP was promoted.

- · SAP as suspected fails to address very low energy buildings
- Only looks at building fabric losses, heating and ventilation
- Cannot engage with weatherproof entrance porch, sunspaces and trembe walls
- · Cannot address roof, sunspace and party wall labyrinth heat recovery systems
- · Cannot see a result for adding insulated roof above an insulated ceiling

- · Most schemes are individual properties
- Many Semi-detached and terrace ends
- Cannot address the party wall adequately
- May actually cause risks at the party wall/external wall junction.
- This project will highlight the inevitable problems and may interpret them badly.

© NGS+ECH2O 2010 BrianMurphyCathHassellRetrofittin





































